

# WIN-911 Release Notes

All notable changes to WIN-911 Advanced/Interactive/Standard are documented in this file.

Product Release: 3.18.2

Release Date: 2018-02-05

- New Data Source Support! Wonderware InTouch 2017
- New Product Release! WIN-911 V7 Configuration Importer
  - Utility used to migrate most data from WIN-911 Version 7 to WIN-911/Standard, Interactive and Advanced. Support data includes: Contacts, Groups, supported notification methods, and supported data sources.
- Dispatcher Module
  - Renotify on any state change can now be disabled on Basic Strategies.
  - Automatic Acknowledgement can now be configured on Basic and Advanced Strategies without utilizing Advanced Tactics.
  - Corrected an issue that caused a new Strategy to start even though the initial event matched a Stop Strategy policy.
  - Corrected an issue that caused Schedules to incorrectly on or off duty due to unique combination of the start day and multi-week recurrence intervals.
- Voice Notifier Module
  - Voice will automatically recover when a TAPI modem is disconnected and then reconnected to the system.
  - Voice will automatically recover from a lost TAPI modem connection due to a failed outbound call.
  - Corrected an issue that caused configured VOIP prefixes to be ignored.
  - Corrected an issue that caused Voice Gateway single codec setting to be ignored.
  - o Added "Auto Nat" discovery enable for VOIP.
  - VOIP is now streamed in audio instead of audio & video, which caused a problem for some VOIP servers only allowing audio calls.
- Email Notifier Module
  - Corrected an issue which prevented acknowledgements with password using HTML formatted emails. This issue effected some mail servers, including MS Exchange 2016.



- Corrected an issue which prevented the relaying of an ack comment without an acknowledgement password using HTML formatted emails. This issue only effected some mail servers, including MS Exchange 2016.
- Corrected an issue that caused HTML formatting to fail when installed in one of the 9 language supported operating systems.
- SSL option can be configured to allow for email servers that are using invalid and expired certificates.
- Tag names that contain 3 or more consecutive numeric characters in their name will no longer be misinterpreted as the ticket number associated with an incoming Ack email.
- The 'Test Incoming Server Settings' and Password button cosmetic issue has been corrected.

#### • iFIX Source Module

- Improved internal method for Acknowledgements so acks for foreign languages will always work.
- o Improved usability of node list selection control.
- Correct an issue that with localized date & time formats that caused new alarm lifetime IDs to be generated, resulting in duplicate alarm events in the Log Viewer.
- o 'No Data' events will be treated as COMM alarms.
- Removed unnecessary dialog asking to shut down the WPF runtime application during uninstalls, so that upgrades will run smoothly.
- Corrected an issue that caused the selected Strategy during Block imports to revert to the default after additional selecting and adding additional Blocks.
- Priorities column for sorting added to Block import.
- Runtime now updates Inactive and Unacknowledged alarms when created just like at startup.

### • WIN-911 Log Viewer

- Users can now hide all controls and disable the ability to Acknowledge an alarm from within the Log Viewer application.
- o Labels are now presented for alarms in the Log Viewer.

# Additional Changes

### **Dispatcher Module**

- Decision Block true false outputs now color coded.
- Corrected an issue which prevented multi-delete of Advanced Tactics.
- New Built-in Basic Strategy for Automatic Acknowledgement without notification.



• Corrected an issue that allowed a 'Save' attempt without a name defined for the Advanced Strategy.

#### Install Launcher

- Windows editions containing "Embedded" in their name will no longer be accepted as a valid install target.
- Windows editions containing Chinese characters for "Pro" are now supported.
- When CodeMeter version 2.51 or 2.51b are detected on the target system the Launcher will now refuse to continue the install unless CodeMeter is upgraded to version 6.20 or newer.

#### <u>Installer</u>

- Modified service start order for SQL instances created by the installer to ensure smoother start up with less potential to log first pass failures.
- Improved SQL Server Input Step to make selection of unnamed SQL instances easier.
- The SMS Module install will detect if there are any startup or shutdown scripts defined for the local Group Policies. If the system is virgin it will attempt to setup a shutdown of the SMS runtime service to take place when the system is shutdown or restarted. Information about the install setup will be contained in the SMS Module install log file. This will insure the connection with a Ethernet/IP cellular modem is properly disconnected when the WIN-911 computer is shutdown.
- The Email Module install will now add a new certificate to the local store and make the required edits to the registry to support Connection HTML format previews for Chinese.

#### FactoryTalk Source Module

- Corrected an issue that caused exceptions at startup when the 'Contains' filter on 'Alarm Class' is defined.
- Subscription behavior adjusted for how Class and Name filters match multiple criteria defined.

#### OPC Source Module

• Editing an existing Server Class name for an OPC DA source can now be saved.



#### **iFIX Source Module**

- Runtime application no longer allows multiple copies to run.
- Runtime tray icon now has a tooltip that contains version.
- Runtime window text updated without reference to "Enterprise".
- Watchdog definition no longer allows invalid values to be entered.
- Corrected cosmetic issues for Block workspace.
- Improved error message generated when iFIX is using security and WIN-911 is not.

#### InTouch Source Module

• Subscription behavior adjusted for how Group and Tagname filters match multiple criteria defined.

#### System Platform Source Module

• Subscription behavior adjusted for how Area and Object/Attribute filters match multiple criteria defined.

#### SMS Notifier Module

• A new setting in the SMS Gateway will allow you to limit maximum text message length to 70 characters.

### Email Notifier Module

- Improved UI for SMTP servers not using authentication.
- The default Email Report format has been changed to 'HTML'.
- Corrected an issue that caused the edit mode Outbound Gateway test to fail.
- Corrected formatting errors in the 'Plain Text Long Vertical Report' format template.
- Cosmetic issues with 'Test Incoming Server Settings' and 'Password' button have been corrected.

### Voice Notifier Module

- Improved TAPI modem disconnect/reconnect logging.
- Voice no longer returns an empty list of Reports
- Prevented the excessive Event Viewer logging that was produced when a TAPI modem was removed.
- Additional information logging was added for VOIP.
- Selected TAPI modem name now saves correctly.



- Relabeled RTP ports definition for minimum and maximum and set controls for new defaults.
- Voice previews in Gateway and Connections now available.
- Maximum time for looped audio request for input were shortened to help Voice connections get serviced faster.
- New Voice formats defined for connections will now present their preview when not in edit mode.
- Voice now reports a failed call if the line is not answered or no code is entered.

#### <u>Workspace</u>

• The WIN-911 GUI for all workspaces now supports Chinese character input.

# Product Release: 3.17.17 Release Date: 2017-09-20

- Added support for Microsoft Windows Server 2016 Standard and Data Editions
- iFIX Source Module
  - o Official support for GE Digital iFIX 5.9
- WIN-911 Log Viewer
  - Added a Notifications view to provide a single timeline for tracing alarm events and their notifications
- Email Notifier Module
  - o Extended support for server configurations not using authentication
  - o Improved handling of incoming invalid messages
  - Corrected a localization issue with IMAP which prevented inbound email functionality in many non-English cultures
- OPC-DA Source Module
  - Corrected an issue which prevented activation or inactivation of Quality alarms
  - Certified automatic reconnection against Citect, ClearSCADA, FS Gateway, and KepServer OPC Servers
  - Configuration changes to Condition Descriptions and Labels now take effect immediately



# Additional Changes

### <u>WIN-911 Log Viewer</u>

- SQL accessibility issues now provide the user with a descriptive message
- Corrected an issue which caused the Log Viewer to become unresponsive when left running for long durations
- Added an Ack Page button
- Improved default layout of several tabs
- Added item count to all main views
- Corrected an issue which prevented multiple selection
- Log Database name made unique to support multiple WIN-911 systems sharing the same SQL server
- Localized Alarm State descriptions
- Localized grid grouping header
- Corrected right-to-left layout for Arabic and Hebrew cultures

### Dispatcher Module

- Corrected an issue which could cause an additional block to execute after stopping an advanced tactic
- Corrected an issue which could cause Dispatcher to wait unnecessarily for timeout on synchronous notification attempts when notifiers reported failures immediately
- Corrected an issue with advanced tactics which prevented modification of the associated connection in copied notification blocks
- Improved memory usage for asynchronous notification
- Improved layout of Strategy workspaces

### SMS Notifier Module

- Improved response time for failed gateway tests
- Runtime no longer removes the "+" character from the country code

#### Navigation Module

- Improved error dialog for unmapped systems
- Rebranded configuration UI as "WIN-911 Workspace"
- Configuration UI shortcut now opens in Internet Explorer instead of default browser



# Product Release: 3.17.14

# Release Date: 2017-08-07

# **Release Highlights**

- Improved Voice Notification Behavior
  - Acknowledgement events are no longer dispatched to Voice Connections that are named as the actor of the acknowledgment
  - Individual Strategies now provide the option to suppress Re-Notify of all Voice Connections for inactive and/or acknowledged events, allowing WIN-911 v7 TAPI behavior without impacting other Notifier types

### • Streamlined Installation

o Reduced installation time for prerequisites and Dispatcher

### • Extended System Platform Support

- o Added support for Wonderware System Platform 2012 R2 SP1
- o Added support for Wonderware Patch 02 for System Platform 2014R2

# • WIN-911 Log Viewer

- Underlying data store changed from LocalDB to SQL Server to improve performance and prevent upgrade issues
- Fixed a cross threading issue which could prevent automatic refreshes in live mode

# Additional Changes

### Dispatcher Module

- No longer able to sort Connections in Basic Tactics, removing confusion resulting from the callout order not matching the displayed sort order
- Now displaying busy animation while fetching Connections in Basic Tactic workspace
- Deleted Connections no longer remain in unsaved Tactics upon return to the Tactic workspace
- Improved the readability and display of long descriptions for Advanced Tactics
- Corrected a UI problem which sometimes prevented the Delay Between Retries controls to become stuck in disabled mode
- Improved memory usage of runtime



#### Install Launcher

- Added additional icon resources to ensure that icon always appears in Windows taskbar
- Now validating amount of RAM

#### <u>Installer</u>

- Corrected an issue during Source module selection which could curtail the display of all validation warning messages when multiple sources were selected for install
- Improved the text displayed upon encountering MS Install Engine error 1618 to suggest that users wait for another installation to complete
- Improved instructions for module selection
- Improved instructions for SQL selection
- Improved instructions for user selection
- Added a warning to inform users of the need to install the Mobile-911 Server product whenever the Mobile-911 module is selected for install

#### **iFIX Source Module**

• Improved detection of disabled blocks

#### InTouch Source Module

- Corrected a thread safety issue which could potentially cause alarm lifetimes not to be expired upon multiple concurrent termination events
- Changes to Subscriptions are now treated the same as changes to Routes and force a resync to avoid runtime behavior not matching expectations
- Relaxed Server validation to allow support for remote servers in a Terminal Services environment
- Now logging Suitelink Suspend and Resume messages as warnings rather than errors

#### System Platform Source Module

- Relaxed Server validation to allow support for remote servers in a Terminal Services environment
- Improved validation error message text



#### WIN-911 Log Viewer

- Corrected an issue which prevented the display of events for alarm point names exceeding 127 characters
- Changed log source value for Windows Event Viewer logging by this utility

# Product Release: 3.17.12 Release Date: 2017-07-10

# **Release Highlights**

- Wonderware System Platform Source Module (version 2014 R2)
- Improved Main Installer
  - Updated InstallShield to correct an access violation issue causing it to fail to extract all prerequisites for installation in Windows 7 and Server 2008 R2
  - Now delivers the full user manual (PDF) with a shortcut
  - Improved Admin Group validation for Domain users in Windows 7 and Server 2008 R2 and 2012 R2
  - Added new warning messages about individual source module dependencies
  - Prevented 'DotNetCoCreateObject' failures when loading in the presence of older CodeMeter installations
  - Implemented robust invalid character syntax checking for user login definition
- Improved OPC DA Source Module
  - o Certified FSGateway support
  - o Alarm Condition Names now update dynamically
  - o Correction for Report value timestamps
  - o Improved Event Viewer logging with tag names

# Additional Changes

### Install Launcher

- Added logging, including report of version
- Added timeout to enable features logic to compensate for Windows 10 updates which cause IIS enable to fail to return
- Corrected Launcher behavior for failed SQL installs so it will not continue and launch the Main installer



#### <u>Installer</u>

- Improved cursor focus for user login password field
- Now reports Release version in logging
- Added a 'Show Password' checkbox for user credentials
- Corrected unsupported Windows OS edition validation
- Improved Windows Authentication logging
- Improved wording for no Application Initialization detected and Windows Update service warning messages
- Added Release version information to GUI dialogs
- Added support for unnamed instances to SQL 'Browse' (shows only computer name)

#### OPC-DA Source Module

- Corrections for View mode (non-edit) cosmetics
- Cosmetic improvements to UI for Grouped Sources
- Correction to prevent more than one source defined for a Basic license

#### Module Mapper Application

- New GUI allows users to view networked Logical Systems
- The Mapper requests local URLs upon refresh to improve completeness of set
- Added localization for foreign cultures (Arabic, German, German Germany, Spanish, Spanish Spain, Spanish Mexico, French, French Canada, French France, Hebrew Israel, Italian Italy, Portuguese and Chinese Simplified)
- Added online help

### EERemove Utility

- Added Logging
- Added System Platform Module

### ServiceActivator Utility

- Improved user feedback including reporting version
- Added System Platform Module to set of requested URLs

#### AdminGroupTest Utility

• Added to distribution Support folder



# Product Release: 3.17.5

# Release Date: 2017-03-14

- Human Translations for Chinese, French, and Spanish.
- Navigation Module Improvements
  - New System Info Workspace allows users to view their Serial Number and edit their Support Code
- FactoryTalk Source Module Improvements
  - Replaced Filters with Subscriptions, which are reusable across multiple FactoryTalk Source objects.
  - Added "Contains/Does Not Contain" to filter types to complement Regex and Wildcard
  - Added support for multiple licensed Source objects
  - Corrected an issue which could cause terminal alarms to be passed to Dispatcher as new events
  - Corrected an issue which caused alarm events to be visible only in history mode after configuration changes
  - Corrected an issue which caused watchdog alarms to repeatedly activate with each connection attempt
- Dispatcher Module Improvements
  - Corrected validation of Strategies to prevent saving objects without a stop strategy policy
  - Corrected a localization issue which caused Strategy Policy Actions to not be visible in Chinese
- Voice Notifier Module
  - Corrected a race condition which could cause multiple concurrent call attempts to the same phone number when using VOIP with multiple channels
- InTouch Source Module
  - Corrected initialization failures and shutdown errors for configurations with only discrete tags
- Improved Installer
  - Application Initialization conflict with KB3125574 now detected and relayed to user



• Improved SQL browse to prepopulate with value selected in a previous install or the recently installed SQL Express

# Additional Changes

#### Mobile-911 Notifier Module Improvements

- Minor improvements and changes for compatibility with future releases.
- Corrected an issue which would cause newly created formats not to preview correctly on the Connection workspace
- Improved Test Busy Indicator

### <u>Installer</u>

- Improved prompt offering SQL Express installation
- Installer now requires entered WIN-911 User to be fully qualified to avoid ambiguity
- Improved module selection validation
- Next Button now disabled on WIN-911 User entry step while Password field is empty
- Improved SQL Installation failure handling
- Installer now handles Windows usernames with spaces
- Corrected an issue which could cause OPC to fail to start with an error indicating it was unable to load 'x86\_OpcLabs.EasyOpcClassicRaw\_5.21.101.1.dll'
- Provided busy indicator while enabling XPS viewer

### FactoryTalk Source Module

- Updated navigation link icon
- Corrected a localization issue which caused the Test Connection button text to appear untranslated.
- Corrected an issue which caused the validation warning "The field Lower-Bound must be between 1 and 1000" to be displayed erroneously
- Corrected an issue which caused application changes not to be saved as expected

### OPC-DA Source Module

• Corrected an issue in installer which could cause OPC to fail to start with an error indicating it was unable to load 'x86\_OpcLabs.EasyOpcClassicRaw\_5.21.101.1.dll'



# Product Release: 3.16.23

# Release Date: 2017-01-04

# Release Highlights

- Improved Installer
  - o Windows features now enabled automatically
  - o Improved SQL detection, with more flexibility
  - o Improved performance for faster installs
  - More accurate environment validation ensures install stops immediately if OS or hardware is unsupported
  - Improved environment validation to communicate all aspects of environment which do not meet requirements
  - o Streamlined launcher UI for faster installs and upgrades with fewer clicks
  - o Application Initialization now installed to Windows 7 Enterprise
- InTouch Source Module Improvements
  - Corrected an issue which caused alarm items contained in reports to be incorrectly reported as inactive and acknowledged.
  - Corrected an issue which caused alarm requests from Mobile-911 to time out against InTouch.
  - Corrected an issue which affected the import of Analog tags deviation and rate of change alarms now honor the strategy specified in the Import UI.
  - o Improved Dynamic Runtime handling of tag/filter deletion
  - o Improved Dynamic Runtime handling of Imported tags
- Dispatcher Module Improvements
  - Corrected validation of Strategies to prevent saving objects without a stop strategy policy

# Additional Changes

# Installation Executable

- HTTP Activation no longer required feature in Windows 7 and Server 2008R2
- Improved error and warning messages
- Cosmetic improvements



#### **Dispatcher Module Improvements**

• Improved behavior of strategy execution during license violation

#### Navigation Module Improvements

- Help now context sensitive for the following workspaces:
  - o System/Standby
  - o Notification/Tactics/Basic
  - o Alarming/InTouch
  - o Contact/Email/Formats
  - o Contact/SMS/Formats
  - o Contact/Voice/Formats
  - o Contact/Mobile-911/Formats
- Improved Help for System workspaces

# Product Release: 3.16.20 Release Date: 2016-11-14

- WIN-911 now provides a direct connect Source module for Wonderware InTouch 10.1, 2012, 2012 R2, 2014, and 2014 R2.
  - Network Access to InTouch Application allows WIN 911 to be installed on a separate machine.
  - o Access multiple InTouch Applications from a single WIN 911 system.
  - Subscription-based alarm eliminates need for import and maintenance of tag definitions.
    - Filter alarms based on Tagname, Group, and Priority.
    - Support for labels for advanced notification.
    - Share subscriptions across applications.
  - o Support for all alarm types: Discrete, Level, Rate of Change, and Deviation.
  - o Support for all data types: Analog, Discrete, and Message.



- o Support for Watchdog alarms on changing data or alarms.
- Dynamic alarm details including descriptions, priority, and groups are configured only in SCADA.
- o Ack Requests forwarded to SCADA (Actor/Comment are WIN 911 only).
- OPC Source Module Improvements:
  - o Added multi-delete to Tags workspace.
  - Import workspace now refreshes to reflect changes made to Server tag configuration.
- SMS Notifier Module Improvements:
  - o Added login support for more secure communication with Ethernet modems.
  - o Improved error logging and recovery for Ethernet modems.
  - o Corrected issue which caused gateway initialization to fail.

# Additional Changes

# Installation Executable

- Improved User Credential Validation to restrict invalid entries.
- Improved SQL Validation.
- Added support for remote SQL Server in workgroups.
- Added InTouch Source module installer.
- Corrected OPC Source module installer issue which left residual registry values upon uninstall.

### OPC-DA Module

- Disabled multi-selection on host machine, server name, and item name browse dialogs.
- Corrected an issue which prevented quality alarms from being saved in Chinese localization.
- Corrected View-mode display of long Source descriptions.

### Navigation Module

• Corrected identity of Runtime in Windows event viewer



#### Product Release: 3.16.15 Release Date: 2016-08-23

# Release Highlights

- WIN-911 now supports hot backup with scripting
  - Standby/Activate/IsActive behavior matches v7 for easy porting of existing scripts.
  - o Previous Activate behavior preserved as new "Reset" option
- Voice now reconnects in the event that a connection to your SIP server is lost
- Enhanced synchronization with iFIX data sources
- Improved default file and folder permissions for enhanced security
- Improved installation and setup documentation
- Localization Improvements

# Additional Changes

# Installation Executable

- Modification made to uninstall leftover objects in Windows 7 Pro
- Visual C++ 2015 redistributable no longer installed if compatible version is already present on system.
- Improved text for .NET Framework 3.5.1 requirement message.
- Improved "Read install Guide" message when no PDF reader exists.

# Voice Module

- Corrected a serious issue preventing callout in user systems with more than 100 voice connections due to an SQL Query being too long.
- Modified TAPI modem discovery logic to prevent modem setting from becoming lost on change to COM port, server restart, server sleep, or virtual server reconfiguration.



### OPC-DA Module

• Selection of multiple items no longer allowed in browsing for OPC server or host.

### GE iFIX Data Source

- Corrected an issue in which edits to the iFIX block configuration while running resulted in orphaned alarm events.
- Watchdogs/Filters can be deleted in iFix without restarting WIN-911
- Dramatically improved speed of large imports.
- Clarified error message where "No nodes are defined on the iFIX runtime" was appearing.
- FIX import workspace allows users to import from specific iFIX nodes rather than all nodes.
- Corrected a race condition which sometimes prevented blocks from appearing in the iFIX import workspace and made the refresh of this collection unreliable.
- Subscription filters now function with Chinese and Arabic (wide character) tag names.
- Correction made to prevent duplicated alarms from subscription filters
- Acknowledgement request for already acknowledged, non-terminal alarms will now be rejected by WIN-911.
- iFIX import warning clarified
- Improved visual styling of scrollbars in GUI.
- Improved control tooltips in GUI.

### Dispatcher Module

- Selection of multiple items no longer allowed in child dialogs where a single item should be selected from a collection (e.g. single notification block of advanced tactics).
- Improved localization of Strategy and Tactics workspaces for non-English speakers.
- Corrected an issue which caused the save button to be incorrectly enabled on the Strategy workspace.



#### Log Viewer

- Data store access modified to allow writing to the log by different windows credential sets.
- Improved feedback when attempting acknowledgement.

#### SMS Module

• Corrected a race condition in the SMS module which could rarely cause module failure (unhandled null reference) upon startup, modem configuration changes, or GUI modem tests.

#### Email Module

- Default SSL port for IMAP changed to 993.
- Improved localization of email interaction for non-English speakers.
- Modified included formats to better present report errors.

#### Reporting Module

• Improved error response when requesting non-existing report

#### Mobile-911 Module

• Improved control tooltips in GUI.

# Product Release: 3.16.9 Release Date: 2016-06-06

- Improved Database Performance
  - Improved workspace performance and load time for larger data sets, especially alarms and connections.
  - o Improved runtime performance.
  - o Improved database performance across all modules.
- Added Custom Formats



- Added a user defined custom format definition workspace to all notification modules.
- Customized notification templates are now available where company logos and alarm/report attributes can be added, reordered, or removed.
- This functionality allows creation and/or edits using raw XSL for description and body for alarms and reports for all notification methods.
- New Documentation
  - User instructions for backing up, restoring and moving the configuration.
  - o Source module alarm event mapping.
  - o Quick Start Guide.
- Windows 10 Support
  - o Enterprise now supports the latest version of Windows 10 OS
  - o WIN-911/TAPI/USB modem not supported\* (check website for future updates)
- Localization for Other Languages
  - Enterprise now supports the following languages/cultures:
    - English

French

German

Hebrew

- Arabic
- ItalianChinese

Portuguese

Spanish

# Additional Changes

# <u>All Modules</u>

- Updated Enterprise Install Environment
- Corrections and modifications that implement Application Pool thread safety at the core level and in each module.
- Save operations are now prohibited while other save operations are pending to ensure data integrity.
- Improved validation in GUI to better indicate which tab an invalidation error is occurring on.
- Optimized sizes of all child dialogs.

# Installation Executable

• Modification made to include latest copy of CodeMeter licensing install in the Enterprise Support folder.



- Three new prerequisites were added to the main install to support the Log Viewer
- Improved database initialization logging.
- Install Upgrade: Change made to prohibit warning from showing up for FactoryTalk Alarm & Events without OPC-DA.
- Change ownership of WIN-911 log database to facilitate sharing as any user
- Fixed item to increase memory for WIN-911 Event Logger in applications and services
- Added message informing user that Windows user requires SQL system administration rights.
- Improvement made to installer to require entry of domain\username and prohibit user@domain syntax
- Reporting module is now installed by default.
- Improved installer guidance in Enterprise upgrades; user is now required to upgrade all installed modules when upgrading to a new major version.
- Improved user validation in Enterprise Edition install.

#### Voice Module

- Voice gateway workspace; cancelation of initial edit no longer results in blank workspace.
- Corrected voice preview for Alarm Format under Contact -> Voice -> Connections, only the Microsoft voices and the WIN-911 English (US) voices were appearing in preview mode. All available premium voices are now able to be previewed under voice connections tab.
- VOIP requirement removed when using authentication.
- Prefix field added in the voice gateway settings.
- Voice during Verbalization of Report Items, previously by pressing digit 1 or 9 would return user to main menu. Change made to for return to main menu command by pressing 0.
- Added dialing prefix in Voice gateway settings.
- Fixed item that was causing reports to be omitted when certain reports numbers were requested.
- Voice module now utilizes SQL database to prevent redialing after a restart is executed. This will allow for improved functionality with Enterprise restarts.

### Dispatcher Module



- Fixed item for a Basic Tactics where a delay was not disabled when Retries set to "0"
- Cosmetic fix made to long report names on advanced tactic screen.
- Fixed column widths on Basic Tactic Screen.
- Fixed item where numerous Dispatcher Logger warnings were showing up in Event Viewer.

### Email Module

- Fix made to Email Diagnostic Alarm Format to prevent missing values.
- Fixed item in Email acknowledgement which sometimes prevented acknowledgement request.

#### Reporting Module

• Added tool tips to Reporting screen.

### Mobile-911 Module

- Fixed Format "Text Short Condition" fields to align properly.
- Fixed item in Mobile-911 where alarm format list was not auto refreshing upon request.

### SMS Module

• Change made if an active SMS modem disappears from Enterprise GUI a notification failure will now be generated.

### <u>Log Viewer</u>

- WIN-911 Log Viewer can now be executed under any local Windows user session.
- Dispatcher shutdown now logged to log viewer as strategy event.
- Modification made to include Strategy Name on strategy tab of Log Viewer.
- Log viewer will now show all failed acknowledged attempts in log database.
- Fixed item where active unacknowledged alarms were disappearing from Log Viewer window
- Fixed item in the Log Viewer where auto acknowledged alarms have no entry in the Acknowledgement tab.

### OPC-DA Module



- OPC-DA: Remove Strategy Name from Condition Properties Entities.
- Improved functionality with multiple remote OPC-DA servers.
- OPCDA module: Alarms workspace was modified to allow search on items without alarm conditions.

### <u>GE iFIX Module</u>

- Fixed item for queue read alarms, where Labels were not being shown.
- Checkbox added to ignore COMM Alarms from data source.
- Modification made for WIN-911 Priority Mappings for iFIX;
  "1-1000" match iFIX definition of High to Low. If severity "1" is High,
  WIN-911 should see "1" as the highest priority.
- Field modifications made to prevent WCF errors from occurring in the Event Viewer.
- iFIX Import Modification: Fixed item for Imported Blocks that were not showing until refresh was executed.
- iFIX Watchdog field added to explain the definition of a "watchdog" and how a "watchdog" is defined.
- Fixed item for GE iFIX setup where Import screen was not showing message about default strategy on a new install.
- Modification made to search bar to correct issue where search was staying populated when leaving and returning to import screen.
- Modification created to notify users about iFIX nodes not being detected.
- Modification created when loading screen stops during a large block import.
- Modification made to support mass deletion of Blocks.
- Fixed item to correct email format where limit operator was "&gt" and should have displayed ">"
- Modification made to fix Import screen from deactivating after navigating back to add a new Strategy.
- Improved content for "learn more" section.
- Improvements made to keep WIN-911 in sync with iFIX when blocks go in and out of scan.
- Modification change made to iFIX import workplace text.
- Correction made to prevent error when fetching available strategies; I.E. "Error fetching available strategies. The import cannot continue."
- Dispatcher will now allow labels to change over the lifetime of an alarm. This is especially useful for iFIX alarm Condition Labels e.g. COMM Alarms.



- Improved iFIX Alarm Import with large alarm databases/sets.
- Correction to stay in sync with iFIX if communication was lost and reconnect was made.
- Correction made to Watchdogs; made iFIX alarm lifetimes unique to improve logging.

### GE CIMPLICITY Module

- Automatically refresh the project associated point workspace upon project delete.
- Added new CIMPLICITY Resource Filter and the ability to filter CIMPLICITY alarms on resource attribute
- CIMPLICITY Points now log invalidation on reconnect.

### Rockwell Automation FactoryTalk Alarm & Events Module

- Added checkbox to globally ignore COMM alarms.
- Modification made to fix a service crash with Watchdog & no class defined in watchdog.
- Made alarm lifetimes unique to improve logging for Watchdogs.
- Watchdog class field now required by Enterprise GUI. A watchdog without a class would have previously stopped the runtime.
- Fixed Item in where a watchdog strategy list was not refreshing.
- Fixed issue where FactoryTalk Alarm & Events digital alarms appeared to be orphaned in WIN-911 Log Viewer.
- Fixed item where "Seconds" was repeated for Watchdog alarms received via a voice notification with a TAPI modem and an analog phone line.
- Removed extraneous error logging.

# Product Release 2.16.1 Release Date: 2016-02-08

# **Release Highlights**

• Support added for new Multi-Tech SMS modems which support Ethernet and Serial protocols.



• Basic tactic and strategy work space added for simple escalation instances. This allows the user to configure a simple call-out list for notification.

# Additional Changes

#### Dispatcher Module

• Added Retries to Notification Blocks.

### WIN-911 Log Viewer

- Includes Live and History view modes.
- WIN-911 Diagnostic Viewer, now WIN-911 Log Viewer
- Modification made to fix a service crash with Watchdog & no class defined in watchdog.
- Information auto updates on all screens.
- DB moved to LocalDB.
- Added ability to acknowledge alarms.

### Email Module

- Added Retries to Notification Blocks.
- Acknowledgement mechanism changed to use ticket numbers in place of matching message IDs.
- Added support for some Email to SMS cellular gateways.
- Removed authentication requirement.
- Fixed format alignment and date/time stamp issues.
- Fixed "Report Descriptor" Subject Format which contained invalid XSL.
- Resolved incoming IMAP issue.

#### Voice Module

- Voice calls are now considered complete when the call terminates rather than when a message is heard.
- Added logic to reinitialize TAPI modem if connection is lost.
- Added logic to continuously retry connection to VoIP server.

### **CIMPLICITY Module**



- Added support for CIMPLCITY 9.
- Added support for longer Point IDs.
- Resolved issue where Watchdog alarms could not be acknowledged.
- Resolved issue where all timestamps were in CST.



The most widely used alarm notification platform in Industry and IIoT